≡ febi 30816



to fit:

VW Touareg, Multivan T5, Transporter T5 with 2.5 TDI and 5.0 TDI engines





EN

Alternator Coupling Pulley Kit

Problem

Severe vibrations and unusually loud noises in the ancillary drive area may be the warning signs of imminent failure of the freewheeling alternator pulley.

Cause



The alternator coupling transfers the torque to the alternator and air-conditioning compressor to dampen vibrations between the connected shafts. Belt alignment and service intervals are critical in this respect, when replacing the alternator freewheel and the alternator coupling, the alternator and/or air-conditioning compressor should also be removed. The alternator is fitted together with a bracket. If both components are separated, after fitting, the alternator becomes misaligned. The result is that the alignment is no longer correct and the alternator coupling can break (see Fig. 1). However, a defective alternator freewheel can also cause damage, it causes the alternator coupling to be overloaded, which can lead to it breaking.

2

Solution

As the alternator should not be separated from the bracket, it should be removed and fitted complete with bracket during repairs. febi strongly recommends paying close attention to the service intervals for the alternator freewheel and alternator coupling: in vehicles without diesel particulate filters (DPF), this replacement should take place every 150,000 km, and in those with DPF, every 180,000 km.

febi no. 26958

3



Important

febi also advises that the alternator freewheel should always be replaced at the same time as changing the alternator coupling. We therefore offer the coupling along with alternator freewheel in a complete kit (febi no. 30816 / Repl. no. 070 903 201 E S1).

febi no. 30798 Alternator freewheel (febi no. 26958 / Repl. no. 070 903 201 E) and coupling (febi no. 30798 /Repl. no. 070 903 327 D) are available individually.

For more technical information please visit: partsfinder.bilsteingroup.com