TSB #88

A-2642 BMW X5/X6 (E70/E71) (F15/F16) PROPER INSTALLATION AND INFLATION NOTICE



IMPORTANT NOTICE

PROPER INSTALLATION & INFLATION PROCEDURES MUST BE FOLLOWED TO AVOID PERMANENT DAMAGE TO THE PART. WARRANTY WILL BE VOIDED IF THESE PROCEDURES HAVE NOT BEEN FOLLOWED.

AIR SPRINGS INFLATED WITHOUT FOLLOWING THE MANUFACTURER'S SPECIFICATIONS/NOT SUPPORTING THE VEHICLE WEIGHT CAN CAUSE THE FORCE TO DISTRIBUTE UNEVENLY, WHICH MAY LEAD TO PREMATURE PART FAILURE.



STOP

IMPROPER INSTALLATION EXAMPLES

Technical

Service Bulletin

STOF


Broken lower piston - Air spring is inflated without supporting the vehicle causing the force to distribute unevenly or the lower piston of the air spring has not been mounted correctly.





IMPROPER INFLATION EXAMPLES

Air springs inflated without following the manufacturer's specifications/not supporting the vehicle can cause the force to distribute unevenly, which may result in crimp ring failure.



<u>Arnott[®] is committed to the quality of its products. If you have a question or problem with any Arnott product,</u> please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com. (In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)

REV 01 03/05/2022