

NEW PRODUCT HIGHLIGHT | OCT2019



febi 103206

to fit:
Ford B-Max 2012>, Ford Fiesta 2008, Ford
Ranger 2002 >, Ford Tourneo 2012, Ford Transit
2013 >



EN

Turn Indicator Switch

Function

Steering column mounted switch that operates the direction indicators and main headlamp beam.

Cause of failure

The direction indicator not cancelling due to the switch sticking in one position and failing to return to its central position. This commonly affects the left hand indicator.

For more technical information please visit: partsfinder.bilsteingroup.com