febi 47197, 48897, 81368, 81369



Volkswagen, Audi, Seat, Skoda, various models



Oil Drain Plug and Special Tool

Problem

Plastic oil drain plugs should always be replaced and a special tool is required for their removal and installation.

Cause

The problem has resulted because of over tightening of metal drain plugs, stripping threads and causing oil leaks.

Solution

Plastic sump plugs have been introduced into the Volkswagen, Audi, Seat & Skoda vehicle range. As the plugs are made of plastic it is imperative that the correct tool is used to prevent damage to them.

The plug turns and then clicks into place. A tooth on the plug, and a notch in the face of the sump ensures the plug is locked into the correct position. It can only be fitted correctly and cannot be over tightened.

The special removal tool is available on its own, (febi 81368) or as part of a kit. (81369)

For more technical information please visit: partsfinder.bilsteingroup.com