

WARRANTY INFORMATION

CODE 220157



APPLICABILITY

This warranty is suitable to Ford:

- 1S7U11000BA-BB-BC,
- 2S7U11000DA-DB-DC,
- YC1U11000AA-AB-AC-AD-AE-AF,

Whit engines: Diesel 2.0-2.4L and equipped with dual-mass Flywheel

WARRANTY INFORMATION

The main cause of starter motor failure is due to excessive buildup of metal dust mixed to engine lubricant in the starter drive and solenoid.

The dust is the result of a worn dual-mass Flywheel system and is not a fault of the starter unit.

The Warranty will be void if the starter has been contaminated with metal dust.