

This EGR valve must be adopted to engine controller!

Reason: if there is an error displayed after installation of EGR to the car (e.g. new part not detected or new part no function) then the reason could be that EGR is not adopted to engine controller.

Please find at tester menu function "Adopting of EGR valve".

Adapt valve to the car

