

ContiTech

ATTENTION WITH TENSIONER FIXING BASE – FIAT ENGINES 1.6 16V Timing belt CT879s

Problem:

Wear on the belt side.

Cause:

Incorrect assembly of the fixing screw to the mounting base housing.

Solution:

Correctly position the fixing screw to the mounting base housing, being sure that there is no decentralization in engine timing set so that there is wear on the belt side.

