

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS
PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE
PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

THIS ALTERNATOR IS COMMONLY AFFECTED
DUE TO BELT SLIP. IT IS HIGHLY
RECOMMENDED THAT THE DRIVE BELT IS
REPLACED WHEN FITTING THE ALTERNATOR
TO AVOID PREMATURE FAILURE

FAILURE TO DO SO WILL RESULT IN DAMAGE TO THE DRIVE BELT AND OTHER COMPONENTS AND WILL CAUSE CHARGING FAULTS.

FREE vehicle specific technical information is available by visiting <u>autoelectro.co.uk</u> OR scan this QR code



The Original and Best

Since 1986