SERVICE INFORMATION

HELLA PAGID
BRAKE SYSTEMS

Replacement of T1638-8DB355012-751 (WVA 24306) by T1622-8DB355012-581 (WVA 24306)

Due to a harmonization of the friction materials being used for the references 8DB355012-751 and 8DB355012-581 both parts become interchangeable.

In order to help our customers to decrease complexity we harmonize both references into one, which will cover all applications of 8DB355012-751 and 8DB355012-581

As you can see in the picture below there is no difference in the outer dimensions of the pad. Also the accessories which are included in the box are the same. The material change now makes the pads equal and therefore one of the sets is obsolete and can be replaced.



8DB355012-751 8DB355012-581

As usual, old stock of 8DB355012-751 can be sold out without any problems.

Hella Pagid GMBH | Lüschershofstraße 80 | 45356 Essen, Germany | +49-201-217600-0 | service@hella-pagid.com | www.hella-pagid.com