

## For Citroën and Peugeot: TOOL BOX V03


If you intend servicing a Citroën or Peugeot engine, special requirements have to be met, particularly with regard to the timing gear. There are also a lot of freewheels. That means that the crankshaft and camshaft can only be locked and released using special tools. TOOL BOX V03 offers everything you need for a fast, safe repair to ensure that the engine runs exactly in accordance with the manufacturer's specifications after the repair.

### Contents

- > Locking tools and locking pins for crankshafts and camshafts
- > Counterhold for camshafts
- > Multilingual manual with tool designations, original part nos. and vehicle applications
- > Puller for crankshaft sprocket

### Benefits

- > All tools for all common Citroën and Peugeot engines quickly to hand
- > Made of strong, premium-quality steel
- > Exclusive sets - only available from Continental
- > Organized storage in a robust case
- > 5-year guarantee:  
[www.continental-ep.com/5](http://www.continental-ep.com/5)



The content of this publication is not legally binding and is provided as information only. The trademarks displayed in this publication are the property of Continental AG and/or its affiliates. Copyright © 2019 ContiTech AG. All rights reserved. For complete information go to: [www.contitech.de/disc\\_en](http://www.contitech.de/disc_en)



# Parts list / Area of application TOOL BOX V03

Item	Designation Article no.	Application	Suitable, for example, for	OE no. for comparison
1	Locking pin Ø6, short KL1480-12	Camshaft	<b>Citroën 1.0:</b> Saxo / <b>1.1:</b> C3 III, Berlingo I + II, C2, C3 I + II, Saxo / <b>2.0:</b> Jumper II; <b>Peugeot 1.0:</b> 106 / <b>1.1:</b> 106, 206, 206+, Partner I + II, / <b>1.8:</b> 306 / <b>2.0:</b> 306, Boxer II; <b>Fiat 2.0:</b> Ducato	0153-AB 0132-Z 9041-TZ
2	Locking pin, angled Ø6 KL1480-11	Flywheel	<b>Citroën 1.0:</b> Saxo / <b>1.1:</b> Berlingo I + II, C2, C3 I, C3 II + III, Saxo; <b>Peugeot 1.0:</b> 106 / <b>1.1:</b> 106, 206, 206+, Partner I + II	0132-Q 0132-Y 4507-TA KV109B0112 9767.27
3	Locking pin Ø9.9 KL1380-2222 A	Camshaft	<b>Citroën 1.1:</b> C3 III, Berlingo I + II, C2, C3 I + II, Saxo / <b>2.0:</b> Jumper II; <b>Peugeot 1.1:</b> 106, 206, 206+, Partner I + II / <b>1.8:</b> 306 / <b>2.0:</b> 306, Boxer II; <b>Fiat 2.0:</b> Ducato	0132-R 0132-RZ 0153-AA 7018-TY 7004-TG
4	Locking pin Ø7.9 KL1380-2220 A	Camshaft Camshaft sprocket Crankshaft	<b>Citroën 2.0:</b> Jumper II / <b>2.0 HDI:</b> Berlingo I, Berlingo II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.8:</b> 306 / <b>2.0:</b> 306, Boxer II / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 2.0:</b> Ducato / <b>2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra	0188-M 0153-G 9766.98 0178A 0132AJ1 5711-TA 7014-TN 2.000.023.200 Ø8mm-pin
5	Locking pin Ø7.9 KL1380-2219 A	Camshaft Camshaft sprocket	<b>Citroën 2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso; <b>Peugeot 2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ; <b>Fiat 2.0 HDI:</b> Ducato, Scudo, Ulysse; <b>Lancia 2.0 HDI:</b> Phedra	0132-AJ1 0132-AJ2
6	Locking pin Ø8.4, Ø6.5 KL1380-2218 A	Camshaft	<b>Citroën 2.0:</b> Jumper II; <b>Peugeot 2.0:</b> 306, Boxer II; <b>Fiat 2.0:</b> Ducato	9767.94 0153M 7014-TM
7	Locking pin Ø10 KL1380-2217 A	Camshaft	<b>Citroën 1.0:</b> Saxo / <b>1.1:</b> C3 I-III, Berlingo I + II, C2, Saxo; <b>Peugeot 1.0:</b> 106 / <b>1.1:</b> 106, 206, 206+, Partner I + II	4507-TB
8	Locking pin Ø6 KL1380-2211 A	Fuel injection pump	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II; <b>Fiat 1.9 HDI:</b> Scudo	0188-H Ø6mm-pin
9	Locking pin, angled Ø6 KL1380-2801 A	Flywheel	<b>Citroën 1.1:</b> C3 I-III, Berlingo I + II, C2, Saxo; <b>Peugeot 1.1:</b> 106, 206, 206+, Partner I + II	0132-QY
10	Locking tool for crankshaft KL1380-2602 A	Tensioning tool for ancillary unit belt Chain tensioner for crankshaft sprocket	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II; <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra / <b>2.2 HDI:</b> Phedra	0188-Q2
11	Locking pin Ø4 angled KL1380-2603	Tensioning tool for ancillary unit belt	<b>Citroën 2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra / <b>2.2 HDI:</b> Phedra	0188-Q1
12	Locking pin, angled KL1480-15	Crankshaft Flywheel	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II / <b>2.0:</b> Jumper II; <b>Peugeot 1.8:</b> 306 / <b>1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.0:</b> 306, Boxer II; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.0:</b> Ducato	0153-ZY 0153-N
13	Locking pin, angled KL1380-2215 A	Flywheel	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II / <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra / <b>2.2 HDI:</b> Phedra	0188-Y I 0118-Y LDV104 I 7104-TJ 1.860.863.000 1.970.827.000 18G1632 I 9767.34
14	Locking tool for crankshaft KL1380-2601 A	Crankshaft sprocket	<b>Citroën 2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra / <b>2.2 HDI:</b> Phedra	0188-AH 2.000.020.300
15	Locking pin for tensioning pulley Ø3 KL1380-2228 A	Tensioning pulley	<b>Citroën 1.1:</b> C3 III, Berlingo I + II, C2, C3 I + II, Saxo / <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso; <b>Peugeot 1.1:</b> 106, 206, 206+, Partner I + II / <b>1.8:</b> 306 / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ; <b>Fiat 2.0 HDI:</b> Ducato, Scudo, Ulysse; <b>Lancia 2.0 HDI:</b> Phedra	0153-AL 4200-TH 4224-TAL
16	Locking pin Ø7.7 angled KL1380-233 A	Flywheel	<b>Citroën 2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra; <b>2.2 HDI:</b> Phedra	0188-X
17	Locking pin, angled KL1380-2216 A	Flywheel	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II / <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.0 HDI:</b> Ducato, Scudo, Ulysse; <b>Lancia 2.0 HDI:</b> Phedra	0188-D 7017-TR 0288-D
18	Hexagon head bolt M8 x 80 KL1380-232 A	Camshaft sprocket	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II; <b>Fiat 1.9 HDI:</b> Scudo	0188-E Screw M8
19	Puller KL1380-234 A	Puller for crankshaft belt pulley	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II / <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra / <b>2.2 HDI:</b> Phedra	0188-P 0188-P2
20	Timing belt retaining clip KL1380-237 A	Timing belt retaining clip	<b>Citroën 1.1:</b> C3 III, Berlingo I + II, C2, C3 I + II, Saxo / <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.1:</b> 106, 206, 206+, Partner I + II / <b>1.8:</b> 306 / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra / <b>2.2 HDI:</b> Phedra	0188-K 0132-AK 0153-AK 4533-TAD
21	Locking tool for flywheel KL1380-231 A	Flywheel	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II / <b>2.0:</b> Jumper II / <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.8:</b> 306 / <b>1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.0:</b> 306, Boxer II / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra / <b>2.2 HDI:</b> Phedra	0188-F 0134-AF 0134-Q 9044-T
22	Timing belt tensioning wrench KL1382-1	Tensioning tool	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II / <b>2.0 HDI:</b> Berlingo I + II, C4 I + II, C4 Picasso, C4 Grand Picasso, C5 I-III, C8, Jumpy I-III, DS4, Jumper II, Xsara II, Xsara Picasso / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.0 HDI:</b> 206, 3008, 307, 307 CC, 308, 308 CC, 406, 407, 407 Coupé, 5008, 508, 607, 807, Boxer II, Expert I-III, Partner I + II, RCZ / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.0 HDI:</b> Ducato, Scudo, Ulysse / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.0 HDI:</b> Phedra; <b>2.2 HDI:</b> Phedra	0188-J 0188-J2 5711-TE 0178-E
23	Timing belt tensioning wrench KL1382-2	Tensioning tool	<b>Citroën 1.9 HDI:</b> Berlingo I + II, C15, Jumpy I + II, Xsara II / <b>2.2 HDI:</b> C5 I-III, C6, C8, C-Crosser, Jumper II; <b>Peugeot 1.9 HDI:</b> 206, Expert I + II, Partner I + II / <b>2.2 HDI:</b> 4007, 406, 406 Coupé, 407, 508, 607, 807, Boxer II; <b>Fiat 1.9 HDI:</b> Scudo / <b>2.2 HDI:</b> Ulysse; <b>Lancia 2.2 HDI:</b> Phedra	0188-J1