


# NEW PRODUCT HIGHLIGHT | JAN2020

**SWAG**<sup>®</sup>

## SWAG 30 10 9176

to fit:

Various Volkswagen, Audi, Seat and  
Skoda models



EN

### ADJUSTMENT MOTOR FOR RECIRCULATING AIR FLAP

#### Function

To operate the interior heater recirculating air flap, for the mixture of the air into the cabin, which is operated by the heater controls.

#### Cause of Failure

A clicking noise from behind the glovebox area, after the engine is started. This noise is from the heater recirculation air flap motor, due to a worn gear drive.

For more technical information please visit: [partsfinder.bilsteingroup.com](https://partsfinder.bilsteingroup.com)