

SWAG 30 94 0672

to fit:

Seat Altea, Škoda Octavia,
VW Golf PLUS, Golf V, Passat 5
and more

Repl. No. 03C 109 158 A S1

SWAG[®]

EN



new version
OE reference 03C 109 088 E
SWAG 30 94 5084



Chain Tensioner
SWAG 30 93 6484



Timing Chain
SWAG 30 94 0390

Timing Chain Kit

PROBLEM

Problems with the timing chain in vehicles with 1.4 TSI engines.

CAUSE

The series manufacturer has reported quality problems with the individual components. Worn tools used during production have left behind metal burrs on the chain links. This leads to premature wear on the chain.

SOLUTION

Make sure that you have installed the latest version of the camshaft adjusters. The manufacturer has replaced the camshaft adjusters which have the OE number 03C 109 088 E (SWAG 30 94 5084). The manufacturer explicitly states that the new version must be installed.

ATTENTION

Afterwards, carry out a system update of the engine control unit to ensure that the engine runs properly!

For more technical information please visit: partsfinder.bilsteingroup.com