
A mix-up presents a severe safety risk! SWAG 60 91 9646 SWAG 60 91 9647





SWAG 60 92 2410



Ball joint repair kit

SWAG is your partner for efficient repairs!

The ball joint can be replaced without removing the complete control arm! However, the vehicle manufacturers only sell it with the complete control arm, even though the ball joint is screwed on in production and can therefore be replaced separately.

SWAG offers the right solution!

The repair kit 60 92 2410 contains the ball joint and all bolts and nuts; all of the required quality - it is not necessary to replace the complete control arm. This also saves your customer money.

Attention! Danger of confusion!

The control arms 77 00 430 766 S1 (SWAG no. 60 92 2410) and 77 01 468 883 (SWAG no. 60 78 0006) seem identical on first glance. However, the diameters of the fixing holes are different! The bore holes of control arm 77 00 430 766 S1 (SWAG no. 90 92 2410) have a diameter of 12mm, the bore holes of control arm 77 01 468 883 (SWAG no. 60 78 0006) have a diameter of 10mm. Some parts identification media falsely allocate control arms with 10mm bore holes to these vehicles.

Of course, SWAG's range also inlcudes the complete control arms SWAG 60 91 9646 and 60 91 9647.

For more technical information please visit: partsfinder.bilsteingroup.com