GK[®] – Powered by Performance



Important installation instructions **ATTENTION!**



When installing, the o-rings must be wetted with coolant!

Don't use other lubricant (especially not containing mineral oil), because thereby the seals are destroyed!

Important note: Please, heed the specifications of the vehicle manufacturer

Suitable for:

VW Multivan T5 2.5 TDI VW Touareg 2.5 TDI

Affected engine codes:

AXD AXE BLJ BNZ BPC BAC BLK BPD BPE VW Transporter T5 2.5 TDI AXD AXE BLJ BNZ BPC

Comparable to OE-No.:

070.121.011A 070.121.011C 070.121.011D 070.121.011DX Technical information 09/12

Water pump affected:

980262

Installation instructions:

- The new "O" rings only wet with coolant!
- Use new screws for the coolant pump

Torque:

Fixing screws of the coolant pump

20Nm+90°

Mounting nut for the gear wheel

84Nm

drain screws

20Nm

Lid for the coolant pump

25Nm

www.gk-autoteile.de