


SB0008



Pozor, čtěte – důležité!

Attention, read – important!

Achtung, lesen – wichtig!

CZ

Motor SB0008 obsahuje olejové čerpadlo bez senzoru OE: 55232196 (odpovídá také PG 7.04193.02.0 nebo ET PU0079).

Pokud je motor instalován do vozidla, kde byl původně použit motor s olejovým čerpadlem včetně senzoru, je potřeba olejové čerpadlo vyměnit za číslo 55268633 (také Pierburg 7.03903.03.0 nebo ET PU0119).

DE



Motor SB0008 beinhaltet Ölpumpe ohne Sensor OE: 55232196 (entspricht auch PG 7.04193.02.0 oder ET PU0079).

Wenn der Motor in ein Fahrzeug eingebaut wird, welches ursprünglich mit Motor mit Ölpumpe inklusive Sensor ausgestattet war, ist es notwendig die Ölpumpe gegen eine andere mit Nummer OE: 55268633 auszutauschen (auch Pierburg 7.03903.03.0 oder ET PU0119).

EN


The SB0008 engine contains an oil pump without sensor OE: 55232196 (also matches PG 7.04193.02.0 and ET PU0079).

If this engine is installed in a vehicle which originally used an engine that contained an oil pump with sensor, it is necessary to replace the oil pump with number 55268633 (also Pierburg 7.03903.03.0 and ET PU0119).



PU0079/KS 7.04193.02.0

Olejové čerpadlo bez senzoru.
Oil pump without sensor.
Ölpumpe ohne Sensor.



PU0119/KS 7.03903.03.0

Olejové čerpadlo se senzorem.
Oil pump with sensor.
Ölpumpe mit Sensor.