


SI2019-015

Regarding replacement of 8DB 355 011-481 (T1461) and 8DB 355 016-261 (T2145) by 8DB 355 020-671 (T2268)

In order to help our customers to decrease complexity and to follow various replacements being made by Peugeot in the OES we are optimizing our portfolio.

The 8DB 355 011-481 and 8DB 355 016-261 will be harmonized into 8DB 355 020-671 which covers applications of both part numbers. As a result, an electronical wear indicator is fitted on WVA 24175 and 24134 only.

Please refer to the below pictures:



The existing stock of 8DB 355 011-481 and 8DB 355 016-261 can be sold out without any problems.