

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS
PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE
PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

This alternator is commonly affected by vehicle wiring faults or faults with the engine control module. The fault causes a charging issues with the alternator when it is fitted. The following faults can be experienced depending on the vehicle:

- Battery warning light on or lights flickering
- Low charge rate
- No output
- Surging or pulsing charge rate
- Overcharging
- Failure of one or more electrical systems

Please refer to our website and search the vehicle details if your are experiencing any of the above faults or similar to obtain the cause of the fault and remedial work.

By fitting the alternator with this existing wiring fault you run the risk of causing damage to the alternator. Please ensure any faults and investigated and rectified before fitting this alternator failure to do so may invalidate your warranty.

FREE vehicle specific technical information is available by visiting autoelectro.co.uk OR scan this QR code



The Original and Best Since 1986