

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS
PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE
PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

The vehicle this alternator is fitted to has a known fault which results in the premature failure of the pulley and/or bearings. This fault can also contribute to charging faults which are caused due to belt slippage and can result in the failure of the regulator or rectifier due to a surge of power.

It is recommended that the drive belt system is checked for any defects and the drive belt be replaced when the alternator is replaced if there any signs of belt slip, alternator pulley failure, bearings failure or the alternator has developed a noise.





FREE vehicle specific technical information is available by visiting autoelectro.co.uk OR scan this QR code



The Original and Best

Since 1986