



AUTOELECTRO

Since 1986

STARTER MOTORS & ALTERNATORS

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

NISSAN Starter Motor - AEY2687

MICRA 1.2 PETROL 10 - 17

NOTE 1.2 PETROL 13 - 18

On the above models it is known that the ignition switch/push button can remain in the START/ENGAGED position and does not return/release after the engine has started, resulting in the starter motor remaining engaged and burning out.

The following signs of failure will help determine if the starter motor you are replacing has failed due to the above fault. If any signs of the below are exhibited on the starter motor you are replacing then immediate attention is required to avoid premature failure of the replacement starter motor, failure to do so may invalidate your warranty.

- Blue colour on armature shaft near pinion
 - Rattling inside motor when starter motor is shaken
 - Burnt smell from starter motor
 - Damaged teeth on starter motor
 - Varnish leaked from starter motor
 - Burnt/discoloured/melted/broken wire from solenoid to starter motor body
- Shrivelled label



FREE vehicle specific technical information is available by

visiting autoelectro.co.uk OR scan this QR code



The Original and Best

Since 1986