



AUTOELECTRO

Since 1986

STARTER MOTORS & ALTERNATORS

IMPORTANT THIS PART HAS KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

This unit is commonly returned for failure due to fluid contamination. Depending on the vehicle there are numerous sources of the fluid leak which can contaminate the unit.

It is critical that you visit our website to obtain information and carry out further investigations to locate the leak and rectify it prior to fitting the replacement unit. Failure to do so will cause the replacement unit to fail prematurely and will invalidate your warranty.

Look out for fluid residue, rust build up, distinctive smell and possible burning smell.

This part is covered under a return to supplier warranty, and must be returned back to the manufacturer for assessment in the event of premature failure. If the manufacturer is satisfied the claim is a genuine warranty and failure has occurred due to a manufacturing defect only then will a Credit be raised. Under no circumstances will this part be accepted for credit if fitted.

Your statutory rights are unaffected.

FREE vehicle specific technical information is available by visiting autoelectro.co.uk OR scan this QR code



The Original and Best
Since 1986