

## PRODUCT IDENTIFICATION

Rover 200 5 doors

FI060EU



84 > 10.89		10.89 > 95		96 >	
All models		All models Excl. Diesel E4411		All models excl. 200Vi	
11072		1549 / 11550		11710	
				200Vi 11711	



These shock absorbers do not possess the same operating characteristics



TIGHTENING TORQUES		daN.m
A	Top mount nuts	3.9
B	Top stem nut	4.4
C	Lower pivot nut	3.9

TIGHTENING TORQUES		daN.m
A	Top mount nuts	3
B	Top stem nut	4
C	Lower pivot nut	8