


MDB1907 / MDB2633

As GM has replaced their version of MDB1907 into a new design, we decided to do the same for Mintex.

Therefore MDB1907 will be replaced by MDB2633.

As you can see in the picture below the design differs, but functional areas are not affected from this, so there is no risk of losing performance or comfort. This change goes along with the changes which have been made for the according OES sets as well.



Existing stock of MDB1907 can be sold out without any problems.