

## Mercedes-Benz Actros MP4 air filter E1059L and E1060L01

Last year the OE manufacturer Mercedes-Benz started to replace the air filter of the Mercedes-Benz Actros MP4 with a filter set consisting of filter and housing cover. The part number A0040946904 (Hengst E1060L01) was replaced by the filter set with part number A0040949704.

The changes can be seen in the illustrations below.



A0040946904 (old)



A0040946904 (new)

The new housing cover is equipped with two plastic swords and a pin that prevent the installation of the old air filter A0040946904. After replacing the housing cover, only the new air filter A0040949704 can be installed.

# Service Information

Due to the patent-protected design of the new housing cover, the Hengst replacement filter can no longer be installed.

From a functional point of view, it is not necessary to replace the housing cover. You can continue to use the existing old housing cover for the E1059L (A0040946804) and E1060L01 air filters (A0040946904). This means that you have no restrictions in your choice of replacement filter.

old housing cover  
without sword and pin



A0040946904 (old)

new housing cover  
with sword and pin



A0040949704 (new)

For maximum flexibility, Hengst recommends using the original housing cover and Hengst E1059L & E1060L01 air filter inserts.



E1059L (A0040946804)



E1060L01 (A0040946904)