Protect the engine compartment!









Bonnet insulation mat, e.g. for MB E-Class febi 33054



Bonnet insulation mats and lower engine compartment covers by febi

The low position of the engine compartment exposes it to damage from uneven road surfaces and is particularly vulnerable to speed bumps, road salts or accidents. Debris thrown up from the road can contribute to cracks and damage to the engine compartment cover.

The engine compartment cover is a safety critical component and, in addition to minimising noise, it ensures targeted cooling of the exhaust system (soot particulate filter) and engine compartment using the airflow. It also serves to protect the drive unit, the oil sump and the steering rod.

febi also supplies the insulation mat fixed directly under the bonnet to reduce engine noise and appropriate fixing rivets (e.g. febi no. 34573). The insulation mats are mainly damaged by rodents, fires in the engine compartment or accidents (see photo).

febi offers an extensive range of engine compartment covers and bonnet insulation mats in OE quality.



febi 34573



Attention!

Torn or unsecured engine compartment covers are a safety risk and can become a danger to other road users if lost when driving.

For more technical information please visit: partsfinder.bilsteingroup.com