

Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

| 93010900 | MAKE MARCA | ENGINE MOTOR | CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS | CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL |
|----------|---------------|--|---|---|
| Kilos | VAG VAG | JK - CR - CY CK - CR - CS - CY JF - JK - JP - JR | 4.5 Kpm | 2 Kpm |
| Libras | VAG VAG | JK - CR - CY CK - CR - CS - CY JF - JK - JP - JR | 33 lbft | 15 lbft |

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE www.ajusa.es

AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB www.ajusa.es