

Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

| 93041500 | MAKE MARCA | ENGINE MOTOR | CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS | CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL |
|----------|--------------------------|--|---|---|
| Kilos | FIAT LANCIA LANCIA | 159A6.046 834B.146 834B1.000-834B1.146 | 12 Kpm | 2.5 Kpm |
| Libras | FIAT LANCIA LANCIA | 159A6.046 834B.146 834B1.000-834B1.146 | 87 lbft | 18 lbft |

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE www.ajusa.es
 AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB www.ajusa.es