

Camshaft Tightening Procedure Procedimiento de Apriete de Árboles de Levas

93044100	MAKE MARCA	ENGINE MOTOR	CAMSHAFT PINION TIGHTENING APRIETE PIÑÓN ÁRBOL LEVAS	CAMSHAFT BEARING TIGHTENING APRIETE COJINETE DEL ÁRBOL
Kilos	FIAT LANCIA LANCIA	159A6.046 834B.146 834B1.000-834B1.146	12 Kpm	2.5 Kpm
Libras	FIAT LANCIA LANCIA	159A6.046 834B.146 834B1.000-834B1.146	87 lbft	18 lbft

AJUSA IS NOT RESPONSIBLE FOR ANY UPGRADE AFTER THIS DOCUMENT HAD BEEN PRINTED. FOR MORE INFO, PLEASE VISIT OUR WEBSITE www.ajusa.es

AJUSA NO SE RESPONSABILIZA DE CUALQUIER ACTUALIZACIÓN POSTERIOR A LA IMPRESIÓN DE ESTE DOCUMENTO. PARA MAYOR INFORMACIÓN VISITE NUESTRA PAGINA WEB www.ajusa.es