Important installation recommendation!!

Correct assignment of the enclosed gasket set:

Affected water pump:

P1034

Problem:


When installing the new coolant pump three different sealing rings (O-rings) are required. They differ in size and color. This installation instructions helps to ensure the correct positioning of the sealing rings.

General instructions:

- 1. Only work on a cold engine!
- 2. The cooling system must be well flusched!
- 3. Clean the sealing surface on the engine thoroughly!
- 4. Use only fresh coolant
 -The old coolant must be disposed of properly!
- 5. Please observe the instructions of the manufacturer with regard to compliance of the tightening torques and the order of tightening of the screws!
- 6. Never start the engine without coolant! The dry running destroy the mechanical seal

Important note:


Please note the specifications of the vehicle manufacturer!



Important note:

The supplied gasket set consists of three different sealing rings which differ in size and color

Correct fitting position:



Used in vehicles:

FIAT Ducato 2.3 JTD IVECO Daily III 29L12 29L12V 35C12 35S12 110 Multijet 2,3 D IVECO Daily IV 29L10V 29L12V 29L12 V/P 120 Multijet 2.3 D 29L14C 29L14C/P 35S11V 35C13V 35S13V/P 150 Multijet 2.3 D 40C11V 40C13V/P 35S13DK

comparable to OE-No.: 504033770

INFORMATION:

Appropriate spare parts You find in our online catalog at www.hepu.de

The content of this publication is provided for informational purposes only. The company HEPU Auto Parts GmbH assumes no liability in connection with this publication. Any liability for any direct or indirect damage, damage claims or collateral damage of whatever kind and on whatever legal basis as may arise from the use of the information contained in this publication is, to the extent legally permissible to be refused. © 2013 - HEPU Auto Parts Inc. All rights reserved. The contents are copyrighted and may not be reproduced in whole or in part, without prior written permission.

HEPU Autoteile GmbH Am Kreuzweg 2 D-32689 Kalletal

Tel +49(0)5264 - 6483-40 Fax +49(0)5264 - 6483-44 www.hepu.de info@hepu.de



