

## Fitting instructions for wheel bearing set 713 6783 20

Manufacturer:	Ford
Models:	Escort VII, Fiesta II, Ka, Puma
ltem no.:	713 6783 20 (rear axle)



When changing the wheel bearings on the rear hubs, the hub nut must only be torqued once, checking the torque a second time could increase the torque and apply an unacceptable preload to the bearing.

If the torque has to be checked, then the hub nutshould be unscrewed by at least two turns before retightening to the specified torque.

Figure1: Wheel Bearing Kit 713 6783 20

Make sure that the brake drum is turned in the opposite direction when the nut is being fastened.

## Note:

The hub nut on the left has a left-hand thread and the one on the right has a right-hand thread.

The tightening torque prescribed by the vehicle manufacturer is 260 Nm.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 08.2009 **FAG 0006** Technical subject to change © 2009 Schaeffler Automotive Aftermarket oHG



## For further information:

Phone: +44 (0) 14 32 264 264\* Fax: +44 (0) 14 32 375 760 Info@LuK-AS.co.uk www.Schaeffler-Aftermarket.com \* Calls from within the UK 08457 001100