



## FAG Service Info

# 566074.# and 566834.#

## Classification of FAG Repair Insert Unit (RIU)

Manufacturer: DAF

Part no.: 566074.#  
566834.#

OE no (Wheel hub): 1691621  
1699327  
1388905  
1391615

See parts catalogue for current application

The two FAG repair insert units (RIU) listed above can be used to repair various DAF wheel hubs. In doing so, a complete replacement of the wheel hub can be avoided. It is therefore possible to carry out a timely repair on the vehicle at the optimum cost.

The following information must be taken into account when classifying the two repair insert units (RIU).

**If there is no DAF part number present on the wheel hub, the bearing must be identified by the following dimensions:**

### FAG RIU 566074.#

- External diameter of inner bearing (INBOARD) 125,000mm
- External diameter of outer bearing (OUTBOARD) 125,000mm

### FAG RIU 566834.#

- External diameter of inner bearing (INBOARD) 124,700mm
- External diameter of outer bearing (OUTBOARD) 119,700mm



Image 1: FAG Repair Insert Unit (RIU)

**If there is a DAF part number present on the wheel hub, proceed as follows:**

- DAF part numbers 1691621 und 1699327, use FAG RIU 566074.#
- DAF part numbers 1388905 und 1391615 use FAG RIU 566834.#

**If a DAF dealer specifies DAF part number 1697346 for your vehicle (repair kit including a new wheel hub), please note the following:**

- Depending on the wheel hub installed on the vehicle, both FAG RIU 566074.# and FAG RIU 566834.# can be used
- Only the dimensions can be used to identify the correct FAG RIU

**You want more? We can help!**

Phone: +44 (0) 1432 264 264  
Fax: +44 (0) 1432 375 760  
aftermarket.uk@schaeffler.com  
www.repxpert.co.uk

SCHAEFFLER  
**REPXP**ERT