

Visual differences between the tensioner pulleys for VAG

Vehicle

manufacturer: Audi, Seat, Skoda, VW

Models:

Audi: A₃, A₄, A₆, ∏

Seat: Altea, Cordoba, Ibiza III,

Inca, Leon, Toledo III

Skoda: Fabia, Octavia

VW: Bora, Caddy, Eos, Golf IV,

Golf V, Jetta III,

New Beetle, Polo, Passat,

Touran

Engines: 1.9 TDI, 1.9 SDI

2.0 FSI, 2.0 TFSI

OE-Nos.: (1) 028 109 243 K

(2) 038 109 243 N **(3)** 06D 109 243

(4) 06D 109 243 B

Item nos.: (1) 531 0524 30

(2) 531 0440 30

(3) 531 0678 30

(4) 531 0777 10




Image 1: Improved race coating — item no. 531 0524 30 shown here as an example

As part of our continuous efforts to improve our products, the coating of the drive wheels on the specified tensioner pulleys has been modified.

The new surface is more durable than the old design.

During the transitional phase, we may have mixed stocks of both designs. Both versions fulfil the relevant technical specifications and can be used without restrictions.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at **www.Schaeffler-Aftermarket.com** or in RepXpert at **www.RepXpert.com**.

Issued 11.2009 INA 0046

Technical subject to change © 2009 Schaeffler Automotive Aftermarket oHG

For further information:

Phone: +44 (0) 14 32 264 264* Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com
* Calls from within the UK 08457 001100

