

SERVICE INFO



Material change for deflection pulley 532 0501 10

Vehicle

Manufacturer: Ford, Mazda

Models:

Ford: Escort VII, Fiesta IV, Focus, Galaxy, Ka, Puma

Mazda: 121 III

Engines:

1.25, 1.3, 1.3i, 1.4 16V, 1.6 16V, 1.7 16V, 1.8 16V, 1.8 Di, 2.0i, 2.3 16V

OE Nos.:

Ford: 95WF-19A216-AC (replaced)
95WF-19A216-AD (replaced)
YS4E-19A216-AA (current)
7109163 (replaced)
1112807 (replaced)
1139951 (current)

Mazda: 1E03-15-930A

Part No.:

532 0501 10




Image 1: Previous design made of metal



Image 2: New design made of plastic

The running surface of deflector pulley 532 0501 10 has been changed from metal to plastic as part of our efforts to continuously develop our products.

It is possible that deflector pulleys with metal pulleys as well as plastic pulleys will be delivered during the transition period.

Note:

Despite the variation in design, both deflector pulleys can be used for the vehicles listed in the catalogues without restrictions.

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 04.2010

INA 0059

Subject to technical changes

© 2010 Schaeffler Automotive Aftermarket

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

