



PRODUCTINEORMATION

THREE NEW BF OIL PUMPS FOR MAN

FOR D20.66 AND D26.76 ENGINES (EURO II – VI)

| Vehicle manufacturer: MAN | | Product: mechanical oil pump | |
|--|-------------------------------|------------------------------|---------------|
| Application | Engine | Ref. no.* | BF no. |
| TGA, TGS, TGX, Lion's Coach, Jetliner, Skyliner | D20.66; D26.76 (Euro II – VI) | 51.05103-5036 | 20 1402 20660 |
| | | 51.05103-5037 | 20 1402 26760 |
| | | 51.05103-5038 | 20 1402 26761 |

These BF oil pumps have been developed in-house by MS Motorservice International GmbH and are available exclusively in the aftermarket.

The optimised design prevents the familiar causes of damage that can occur with the oil pumps originally installed ex works.

ALL THE ADVANTAGES AT A GLANCE

- Complete spare parts kit including all necessary screws and gaskets.
- The oil pumps are supplied pre-assembled.
- Increased reliability thanks to improved design with the same performance data.
- Each oil pump is tested on the test rig before delivery.
- Price benefit compared to the OE kit.
- Delivery includes assembly instructions.



20 1402 20660

20 1402 26760

20 1402 26761



MAN oil pumps

All content including pictures and diagrams is subject to change. For assignment and replacement, refer to the current catalogues or systems based on TecAlliance.

* The reference numbers given are for comparison purposes only and must not be used on invoices to the consumer.





Item no. 20 1402 20660

| Component | Number | Ref. no.* |
|------------------------------|--------|--|
| Oil pump cover | 1 | 51.05103-5036; 51.05103-0129 |
| Ring gear | 1 | 51.05104-0251; 51.05104-0246; 51.05104-0233 |
| Oil pump pinion | 1 | 51.05104-0234 |
| Oil pump pinion axle | 1 | 51.05105-5000; 51.05105-0070 |
| O-ring seal 22 x 2 | 1 | 06.56936-1150; 06.56331-0251 |
| Cylinder screw M10 x 35 | 1 | 06.02099-0380; 06.02094-4511 |
| Sealing plug 6 x 5 | 1 | 06.21649-0003; 06.21641-0604; 51.90310-0257; 64.90490-0065; 64-90490-0050 |
| Hexagonal flange screw M6x20 | 9 | 06.03216-8204; 06.03216-6204 |



Item no. 20 1402 26760

| Item no. 20 1402 26760 contains: | | | | |
|----------------------------------|--------|--|--|--|
| Component | Number | Ref. no.* | | |
| Oil pump cover | 1 | 51.05103-5037 | | |
| Ring gear | 1 | 51.05104-0252; 51.05104-0244 | | |
| Oil pump pinion | 1 | 51.05104-0245 | | |
| Oil pump pinion axle | 1 | 51.05105-5002 | | |
| O-ring seal 22 x 2 | 1 | 06.56936-1150; 06.56331-0251 | | |
| Cylinder screw M10 x 35 | 1 | 06.02099-0380; 06.02094-4511 | | |
| O-ring seal 25.12 x 1.78 | 1 | 06.56936-1328 | | |
| Sealing plug 6x5 | 1 | 06.21649-0003; 06.21641-0604; 51.90310-0257; | | |
| | | 64.90490-0065; 64-90490-0050 | | |
| Hexagonal flange screw M6x20 8 | | 06.03216-8204; 06.03216-6204 | | |



Item no. 20 1402 26761

| Item no. 20 1402 26761 contains: | | | | |
|----------------------------------|--------|---|--|--|
| Component | Number | Ref. no.* | | |
| Oil pump cover | 1 | 51.05103-5038 | | |
| Ring gear | 1 | 51.05104-0251; 51.05104-0246; 51.05104-0233 | | |
| Oil pump pinion | 1 | 51.05104-0234 | | |
| Oil pump pinion axle | 1 | 51.05105-5000; 51.05105-0070 | | |
| O-ring seal 22 x 2 | 1 | 06.56936-1150; 06.56331-0251 | | |
| Cylinder screw M10 x 35 | 1 | 06.02099-0380; 06.02094-4511 | | |
| O-ring seal 25.12x1.78 | 1 | 06.56936-1328 | | |
| Sealing plug 6 x 5 | 1 | 06.21649-0003; 06.21641-0604; 51.90310-0257; 64.90490-0065; 64-90490-0050 | | |
| Hexagonal flange screw M6x20 | 8 | 06.03216-8204; 06.03216-6204 | | |