COMPRESSOR SERVICE BULLETIN



INSTALLATION OF THIS AIR SUSPENSION COMPRESSOR REQUIRES THE REPLACEMENT OF THE COMPRESSOR RELAY.

FAILURE TO REPLACE THE OE RELAY WITH THE UNIT PROVIDED IN THIS KIT CAN CAUSE DAMAGE AND/OR VOID WARRANTY.

PLEASE REFER TO YOUR VEHICLES SHOP MANUAL OR
CONSULT YOUR LOCAL DEALERSHIP FOR THE LOCATION
AND PROPER PROCEDURES FOR REPLACING YOUR AIR
SUSPENSION COMPRESSOR RELAY.

Arnott® is committed to the quality of its products. If you have a question or problem with any Arnott product, please contact Arnott by calling 800-251-8993 during normal business hours or email techassistance@arnottinc.com.

(In the EU please call +31 (0)73 7850 580 or email info@arnotteurope.com)