## <u>VCF399</u>

## Makes/ Models

Filter Type:

Standard

## <u>Hyundai</u>

Accent (2000 -> 2006

## **Cabin Filter Location**



Difficulty:	Easy
Time (Approx)	10 Mins

- 1. The cabin filter can be found on the passengers side behind the glove compartment
- 2. Unhinge and remove the glove compartment to show the filter cover behind it.
- 3. Move the wires to one side and unscrew the filter cover to change the cabin filter.