

IMPORTANT PLEASE READ THE INFORMATION BELOW BEFORE FITTING THIS PART AS THERE ARE KNOWN ISSUES WHICH WILL RESULT IN THE PREMATURE FAILURE OF THE UNIT AND MAY INVALIDATE YOUR WARRANTY

There is a known fault with the vehicle that this starter motor is fitted to resulting in in the battery cable to the B+ terminal on the solenoid burning and melting due to the wiring insulation not being correctly heat shrunk.

Please ensure you check the starter motor you are replacing for any damage to the solenoid and terminals. Also inspect the wiring harness for corrosion or damage.

Failure to inspect and replace the wiring will result in premature failure of the replacement starter motor and will invalidate your warranty.



Under no circumstances will this starter motor be accepted for credit if it is returned with a burnt/melted solenoid or burnt terminals.

We have identified part numbers for the replacement wiring, dependant on the vehicle specification. *

Starter motor wiring harness (models with AT)

Starter motor wiring harness (models with MT and stop-start system)

Starter motor wiring harness (models with MT)

95389088 95389089

95389090

*The above part numbers have been provided as information only and a guide to what part number you may require, it is your responsibility to ensure that the wiring you are fitting is correct. Autoelectro cannot be held responsible for the use of the above part numbers.

The Original and Best

37

FREE vehicle specific technical information is available by



Since

