





Das Original

TSI 11/13



Joint d'étanchéité, culasse

# Audi | Seat | Skoda Volkswagen 2,0 TDI CR



898.460



726.740

Das Original	#	#	#	i
<b>898.460</b>	03L 103 383	03L 103 383 M	03L 103 383 AQ	1 ⊗   $\pm$ 1,55 mm
<b>898.480</b>	03L 103 383 A	03L 103 383 N	03L 103 383 AR	2 ⊗   $\pm$ 1,63 mm
<b>898.510</b>	03L 103 383 B	03L 103 383 P	03L 103 383 AS	3 ⊗   $\pm$ 1,71 mm
<b>726.740</b>	03L 103 383 AJ	03L 103 383 BF	03L 103 383 BM	1 ⊗   $\pm$ 1,55 mm
<b>726.840</b>	03L 103 383 AK	03L 103 383 BG	03L 103 383 BN	2 ⊗   $\pm$ 1,63 mm
<b>726.850</b>	03L 103 383 AL	03L 103 383 BH	03L 103 383 BP	3 ⊗   $\pm$ 1,71 mm