





Das Original

TSI 11/13



Guarnizione, Testata

Audi | Seat | Skoda Volkswagen 2,0 TDI CR



898.460



726.740

La Guarnizione Testa Cilindro può essere comparato come di seguito:

Das Original	# (solo per comparazione)	# (solo per comparazione)	# (solo per comparazione)	i
898.460	03L 103 383	03L 103 383 M	03L 103 383 AQ	1 ⊗ ± 1,55 mm
898.480	03L 103 383 A	03L 103 383 N	03L 103 383 AR	2 ⊗ ± 1,63 mm
898.510	03L 103 383 B	03L 103 383 P	03L 103 383 AS	3 ⊗ ± 1,71 mm
726.740	03L 103 383 AJ	03L 103 383 BF	03L 103 383 BM	1 ⊗ ± 1,55 mm
726.840	03L 103 383 AK	03L 103 383 BG	03L 103 383 BN	2 ⊗ ± 1,63 mm
726.850	03L 103 383 AL	03L 103 383 BH	03L 103 383 BP	3 ⊗ ± 1,71 mm